

8 7 6 5 4 3 2 1

F

E

D

C

B

A

F

E




D

C




B

A

WITHOUT CLEANING UNIT



WITH CLEANING UNIT



- NOTES:
1. ENSURE THE SENSOR CANNOT MAKE CONTACT WITH THE TANK WALL.
 2. PROTECT THE PROBE AGAINST THE ONCOMING FLOW OF LARGE OBJECTS, SUCH AS BRANCHES OR ICE AND AGAINST FLOW SURGES.
 3. MAX 3000 MM[118,11] IMMERSION DEPTH.
 4. ENSURE 45° ± 15° ANGLE BETWEEN PROBE AND WATER SURFACE.
 5. USE LZY514 (ADDITIONAL WEIGHT FOR CLEANING UNIT) IF THE CLEANING UNIT IN COMBINATION WITH THE CHAIN MOUNT KIT IS USED.

				Maße ohne Toleranzangaben General Tolerance		Maßeinheit/Dim. unit mm [inch]		Verwendung Application		Maßstab Scale		1:10	
						Volumen/Volume		Werkstoff, Halbzeug: Material:					
						Datum/Date		Benennung / Designation					
						Bearb./Dra.		Kettenhalterung für ISE-Sonden Transmittal-Drawing					
						Gepr./Chk.							
						Rev.-Chk.							