

SS7sc Controller Navigation


sc100 Controller Key Functions/Features

Key	Function
	Moves back one level in the menu structure.
	Moves to the main menu from other menus. This key is not active in menus where a selection or other input must be made.
	Navigates through the menus, changes settings, and increments and decrements digits.
	Moves to the Main Measurement screen from any other screen. This key is not active in menus where a selection or other input must be made.
	Accepts an input value, updates, or accepts displayed menu options.


Important Key Presses

- Press **HOME** then the **RIGHT** or **LEFT** key to display two readings when two sensors are connected. Continue to press the **RIGHT** or **LEFT** key to toggle through the available display options.
- Press the **UP** and **DOWN** keys to toggle the status bar at the bottom of the measurement display to display the secondary measurement (temperature) and output information.
- When in Menu mode, an arrow may appear on the right side of the display to indicate that more menus are available. Press the **UP** or **DOWN** key (corresponding to the arrow direction) to display additional menus


Sensor Setup



Calibration



Verification



FOR TECHNICAL ASSISTANCE, PRICE INFORMATION AND ORDERING:
 In the U.S.A. – Call toll-free 800-227-4224
 Outside the U.S.A. – Contact the HACH office or distributor serving you.
 On the Worldwide Web – www.hach.com; E-mail – techhelp@hach.com

HACH COMPANY
 WORLD HEADQUARTERS
 Telephone: (970) 669-3050
 FAX: (970) 669-2932